

Asbestos Survey Inventory - Perth

Ve r. 2007-05-07/06c056

Location ID	Location Description	Sample ID	Material Sampled	Lab Result	Asbestos Type	Total		
LP006	(blank)	06-1	ceiling tile	Negative	na	1		
		06-10	wall insulation perimeter	Negative	na	1		
		06-11	wall insulation perimeter	Negative	na	1		
		06-12	wall insulation perimeter	Negative	na	1		
		06-13	plaster	Negative	na	1		
		06-14	plaster	Negative	na	1		
		06-15	plaster	Negative	na	1		
		06-16	baseboard	Negative	na	1		
			mastic	Negative	na	1		
		06-17	baseboard	Negative	na	1		
			mastic	Negative	na	1		
		06-18	baseboard	Negative	na	1		
			mastic	Negative	na	1		
		06-19	floor tile	Negative	na	1		
			mastic	Negative	na	1		
		06-2	ceiling tile	Negative	na	1		
		06-20	floor tile	Negative	na	1		
			mastic	Negative	na	1		
		06-21	floor tile	Negative	na	1		
			mastic	Negative	na	1		
		06-22	floor tile	Negative	na	1		
			mastic	Negative	na	1		
		06-23	floor tile	Negative	na	1		
			mastic	Negative	na	1		
		06-3	ceiling tile	Negative	na	1		
		LP009	(blank)	06-1	ceiling tile	Negative	na	1
				06-10	wall insulation perimeter	Negative	na	1
				06-11	wall insulation perimeter	Negative	na	1
				06-12	wall insulation perimeter	Negative	na	1
				06-13	plaster	Negative	na	1
				06-14	plaster	Negative	na	1
				06-15	plaster	Negative	na	1
				06-2	ceiling tile	Negative	na	1
				06-24	drywall compound	Negative	na	1
06-25	drywall compound			Negative	na	1		
06-26	drywall compound			Negative	na	1		
06-27	baseboard			Negative	na	1		
	mastic			Negative	na	1		
06-28	baseboard			Negative	na	1		
	mastic			Negative	na	1		
06-29	baseboard			Negative	na	1		
	mastic			Negative	na	1		
06-3	ceiling tile			Negative	na	1		
06-30	floor tile			Negative	na	1		
	mastic			Negative	na	1		
06-31	floor tile			Negative	na	1		
	mastic	Negative	na	1				
06-32	floor tile	Negative	na	1				
	mastic	Negative	na	1				
06-33	floor tile	Negative	na	1				
	mastic	Negative	na	1				
06-34	floor tile	Negative	na	1				

LP017	(blank)	06-1	mastic	Negative	na	1
			ceiling tile	Negative	na	1
		06-10	wall insulation perimeter	Negative	na	1
		06-11	wall insulation perimeter	Negative	na	1
		06-12	wall insulation perimeter	Negative	na	1
		06-13	plaster	Negative	na	1
		06-14	plaster	Negative	na	1
		06-15	plaster	Negative	na	1
		06-16	baseboard	Negative	na	1
			mastic	Negative	na	1
		06-17	baseboard	Negative	na	1
			mastic	Negative	na	1
		06-18	baseboard	Negative	na	1
			mastic	Negative	na	1
		06-2	ceiling tile	Negative	na	1
		06-3	ceiling tile	Negative	na	1
		06-35	floor tile	Negative	na	1
			mastic	Negative	na	1
		06-36	floor tile	Negative	na	1
			mastic	Negative	na	1
06-37	floor tile	Negative	na	1		
	mastic	Negative	na	1		
LP018	(blank)	06-13	plaster	Negative	na	1
		06-14	plaster	Negative	na	1
		06-15	plaster	Negative	na	1
		06-19	floor tile	Negative	na	1
			mastic	Negative	na	1
		06-20	floor tile	Negative	na	1
			mastic	Negative	na	1
		06-21	floor tile	Negative	na	1
			mastic	Negative	na	1
		06-22	floor tile	Negative	na	1
			mastic	Negative	na	1
		06-23	floor tile	Negative	na	1
			mastic	Negative	na	1
		06-27	baseboard	Negative	na	1
			mastic	Negative	na	1
		06-28	baseboard	Negative	na	1
			mastic	Negative	na	1
		06-29	baseboard	Negative	na	1
			mastic	Negative	na	1
		06-30	floor tile	Negative	na	1
			mastic	Negative	na	1
		06-31	floor tile	Negative	na	1
			mastic	Negative	na	1
		06-32	floor tile	Negative	na	1
	mastic	Negative	na	1		
06-33	floor tile	Negative	na	1		
	mastic	Negative	na	1		
06-34	floor tile	Negative	na	1		
	mastic	Negative	na	1		
06-38	ceiling tile	Negative	na	1		
06-39	ceiling tile	Negative	na	1		
06-40	ceiling tile	Negative	na	1		
06-41	ceiling tile	Negative	na	1		
06-42	ceiling tile	Negative	na	1		

